



BV1-1 の水質モニタリング

資料 4-1 (参考)





観測孔位置図

日付  
工事内容  
施工本数  
累計施工本数

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			



# BV1-2の水質モニタリング



日付  
 工事内容  
 施工本数  
 累計施工本数

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			



# BV1-3 の水質モニタリング



日付  
工事内容  
施工本数  
累計施工本数

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2	杭施工	1	1
3/9	杭施工	1	2
3/16	杭施工	1	3
3/23	杭施工	1	4
3/30	杭施工	1	5
4/6	杭施工	1	6
4/13	杭施工	1	7


# BV2-1 の水質モニタリング



観測孔位置図

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2	杭施工	1	1
3/9	杭施工	1	2
3/16	杭施工	1	3
3/23	杭施工	1	4
3/30			
4/6			
4/13			



# BV2-2 の水質モニタリング



日付  
工事内容  
施工本数  
累計施工本数

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			



BV2-3 の水質モニタリング



観測孔位置図

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			

各孔の EC(mS/m)



日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			